






OK-5120H


ASSEMBLY INSTRUCTION

1. INDOOR USE ONLY.

2. REPLACE THE BULB AFTER THE BULB GETS COOL



①
12PCS



Assembly steps:

Step 1. Hang the bead (①) to ring (E).

Step 2. Hang the bead strings (D) into loop (A2).

Step 3. Ture the bulb (C) into tube (A3)

Step 4. Attach the threaded tube (B) to nipple (A1).

Step 5. Attach the assembly (E) over the threaded tube (B), mont the shade (F) and secure with loop (G).

Step 6. Tighten loop (G) on the tube (I).

Step 7. Loosen screw (J) and pass canopy (K) over the tube (I).

Step 8. Tighten loop (L) on the tube (I).

Step 9. Pass the main wire through the link of china, loop (G), canopy (K), tube (I) and loop (L).

Step 10. Attach first link and last link (H) of chain to the loops (G) and (G)

step 11. Connect wire to the power supply cord.

Step 12. Raise the canopy (K) to ceiling and secure it by tightening the screw (J).

Step 13. Hang the Loop (L) on the hook on ceiling.

After completed the above instruction, please check once more to ensure its safety. Then you may turn the power on. If the external cable or cord is damaged, it shall be replaced by the qualified person to avoid hazard.